



State Water Resources Control Board

June 17, 2016

(Via email and Certified Mail)
CERTIFIED MAIL
NO. 7015 1520 0001 8019 6729

Mr. Ron Lindsey
Operations Superintendent Fleet Services
Department of Public Works
City of Anaheim
955 South Melrose Street, MS #19
Anaheim, California 92805
rlindsey@anaheim.net

SUBJECT:

NOTICE OF VIOLATION; UNDERGROUND STORAGE TANK SYSTEMS LOCATED AT CITY OF ANAHEIM FACILITY AND FLEET MAINTENANCE, 955 SOUTH MELROSE STREET, ANAHEIM

Dear Mr. Lindsey:

As part of an initiative by the State Water Resources Control Board (State Water Board) to ensure compliance at government-owned and/or operated underground storage tank (UST) facilities in California, the State Water Board staff inspected the USTs at your facility on June 9, 2016, pursuant to authority under Health and Safety Code (H&SC), chapter 6.7, section 25289.

The State Water Board has identified the following violations pursuant to H&SC, chapter 6.7, and title 23, California Code of Regulations (CCR), chapter 16:

No.	Violation	Tank	Start Date	Stop Date	Regulation
1	Failure to Maintain Site Map – The site map is insufficient; it does not include location of piping.	All	June 9, 2016	Ongoing	23 CCR 2711(a)(8)
2	Failure to Maintain Operating Permit On-Site – The permit to operate was not onsite during the June 9, 2016 inspection. Corrected same day.	All	June 9, 2016	June 9, 2016	23 CCR 2712(i)
3	Failure to Maintain Testing Records On-Site – The 2015 and 2013 Annual Monitoring Certifications onsite were missing Section 'I' vacuum/pressure monitoring equipment testing section.	All	June 9, 2016	Ongoing	H&SC 25293; 23 CCR 2712(b)

No.	Violation	Tank	Start Date	Stop Date	Regulation
4	Failure to Maintain Spill Containment Requirements – The spill bucket had liquid and debris in it which prevents its ability to hold five gallons.	Diesel	June 9, 2016	Ongoing	H&SC 25284.2; 23 CCR 2635(b)(1)
5	Failure to Maintain Tank System Liquid and Vapor Tight – Liquid was observed in the turbine sumps of unleaded tank #1 and tank #2.	Unleaded Tanks 1 & 2	June 9, 2016	Ongoing	H&SC 25290.1(c)(1),(2), and (3)
6	Failure to Maintain Tank System Liquid and Vapor Tight – Liquid was observed in under dispenser containment 5/6.	Diesel	June 9, 2016	Ongoing	H&SC 25290.1(c)(1),(2), and (3)

You are directed to correct the ongoing violations and submit compliance documentation to the State Water Board and Anaheim Fire & Rescue within sixty (60) days from the date of this letter. Have your Designated Operator make specific notations in the next monthly designated operator report indicating the ongoing violations have been corrected. The monthly designated operator report and any associated photos must be submitted as proof of compliance.

Please send all compliance documentation to the following:

State Water Board

Mr. Will Speth
UST Enforcement Unit
Office of Enforcement
State Water Resources Control Board
1001 I Street, 16th Floor
Sacramento, California 95814
will.speth@waterboards.ca.gov

Local CUPA

Mr. Russ Siems
Hazardous Materials Specialist
Community Risk Reduction Division
Anaheim Fire & Rescue
201 South Anaheim Boulevard, Suite 300
Anaheim, California 92805
rsiems@anaheim.net

Pursuant to Health and Safety Code, chapter 6.7, section 25299, the owner and operator of the tank(s) are liable for a penalty of \$500 to \$5,000 per tank, per day of violation. These penalties will continue to accrue until the violations have been corrected.

If you have any questions, please contact me at (916) 341-5551, or by email at amantha.henkel@waterboards.ca.gov.

Sincerely,

Amantha Henkel

Senior Environmental Scientist

UST Enforcement Unit

Office of Enforcement

cc: See next page.

cc: (via email only)

Mr. Gary Blevins Assistant Fire Marshal Anaheim Fire Department gblevins@anaheim.net

Mr. Russ Siems Hazardous Materials Specialist Anaheim Fire Department rsiems@anaheim.net

Mr. Mike McCarty
Fleet Acquisition Administrator
Fleet and Facility Services
City of Anaheim
mmccarty@anaheim.net

Mr. Steven Lantz
Designated UST Operator
Fuel Systems Testing & Compliance
AW Associates Incorporated
steven@awassociatescorp.com